



BB 'Iso': Left 0mm, Up 0mm, In 0mm


WL G=0, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=21.20, in=-59.64, up=-20.42; Gantry tilt=0, Gantry sag=0.dcm



WL G=90, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=21.60, in=-60.44, up=-18.73; Gantry tilt=0, Gantry sag=0.dcm



WL G=180, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=19.74, in=-58.99, up=-20.99; Gantry tilt=0, Gantry sag=0.dcm



WL G=270, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=18.72, in=-58.84, up=-19.12; Gantry tilt=0, Gantry sag=0.dcm

